


**NOTES:**

**1. OPERATION**

1. GENTLY LIFT LATCH AT SIDE OF CONNECTOR.
2. SWING COVER OFF OF CONTACTS.
3. SLIDE THE FLEX TAPE INTO THE CONNECTOR PLACING THE EDGE OF THE FLEX TAPE UNDER 2 HOLD DOWN TABS.
4. FOLD OVER THE COVER AND PRESS IN PLACE UNTIL THE LATCH IS FULLY ENGAGED.

**2. LIMIT CURRENT TO A MAXIMUM OF 5 AMPS.**

**JKL PART NO.: ZCH-137HD-8J**

			 <p>THIRD ANGLE PROJECTION</p>		<p><b>METRIC</b></p> <p>DIMENSIONS ARE IN mm (INCHES)</p> <p>TOLERANCE UNLESS OTHERWISE SPECIFIED</p> <p>1 PL +/- REF.</p> <p>2 PL +/- REF.</p> <p>ANGLE +/-</p>		<p><b>JKL COMPONENTS CORPORATION</b></p>							
					<p>TITLE</p> <p><b>NO SOLDER 8mm FLEX TAPE JOINER CONNECTOR</b></p>									
<p><b>A</b> ADD SIDE VIEW</p>			<p>8/20/15</p>		<p>DRAWN BY</p> <p>L. WENGSTROM</p>		<p>APPV'D BY DATE</p> <p>L.R. 8/20/15</p>		<p>SIZE</p> <p><b>A</b></p>		<p>FSCM NO.</p> <p><b>55335</b></p>		<p>DRAWING NO.</p> <p><b>ZCH-137HD-8J</b></p>	
<p>RELEASE &amp; CANCEL PL-1409-02</p>			<p>10/10/14</p>		<p>- CAD DRAWING -</p> <p>MANUAL REVISIONS NOT PERMITTED</p>		<p>SCALE</p> <p><b>NONE</b></p>		<p>RELEASED DATE</p> <p>10/10/14</p>		<p>REVISION DATE</p> <p>8/20/15</p>		<p>REV. NO. <b>A</b></p>	
<p>REV. NO.</p>			<p>DESCRIPTION/ECO</p>		<p>APPV'D DATE</p>		<p>SCALE</p>		<p>RELEASED DATE</p>		<p>REVISION DATE</p>		<p>SHEET</p> <p>1 OF 1</p>	