9007CA12



Main

| Range of product | 9007 |
|-----------------------------|---|
| Series name | Heavy duty |
| Product or component type | Limit switch lever |
| Device short name | 9007C |
| Associated head | 9007A 9007B 9007C 9007N 9007T10 9007T5 |
| Associated complete product | 9007AW 9007C |
| Movement of operating head | Rotary |
| Type of operator | Cast zinc spring return roller lever length: 2 in - offset: |
| Type of roller | 1 steel outside roller diameter: 0.75 in - width: 0.63 in |
| Type of approach | Lateral approach |
| Positive opening | Without |
| | |

Complementary

| Switch actuation | By 30° cam | |
|------------------|------------|---|
| Product weight | 0.1 lb(US) | 7 |

Environment

| ambient air temperature for operation | -20185 °F | |
|---------------------------------------|----------------------|--|
| ambient air temperature for storage | -20185 °F | |
| environmental characteristic | Standard environment | |

Offer Sustainability

| Not Green Premium product | Not Green Premium product |
|--|--|
| Will not be Compliant | Will not be Compliant |
| Reference not containing SVHC above the threshold | Reference not containing SVHC above the threshold |
| Available | Available |
| Need no specific recycling operations | Need no specific recycling operations |
| WARNING: This product can expose you to chemicals including: | WARNING: This product can expose you to chemicals including: |
| Diisononyl phthalate (DINP), which is known to the Stat of California to cause cancer, and | e Diisononyl phthalate (DINP), which is known to the State of California to cause cancer, and |
| Di-isodecyl phthalate (DIDP), which is known to the Sta of California to cause birth defects or other reproductive | teDi-isodecyl phthalate (DIDP), which is known to the State of California to cause birth defects or other reproductive harm. |

harm.

For more information go to www.p65warnings.ca.gov For more information go to www.p65warnings.ca.gov

Contractual warranty

| rranty period | 18 months | |
|----------------|-----------|--|
| irranty period | 18 months | |