VM1PPI0047Q

Main

Range of product	Hyde Park
Sensor type	Ultrasonic sensor
Series name	Virtu VM1
Device short name	VM1
Sensor design	Flat form + cylindrical M18
[Sn] nominal sensing distance	20 in (508 mm)
Type of sensing window	Adjustable
Material	Plastic
Enclosure material	Valox
Front material	Glass epoxy
Type of output signal	Analog
ISO thread	M18 x 1
Wiring technique	4-wire
[Us] rated supply voltage	1524 V DC (overload and short-circuit protection)
Supply voltage limits	1328 V DC
Analogue output range	420 mA autoslope
Electrical connection	1 male connector M12 4 pins
Product specific application	-

Complementary

[Sd] sensing range	220 in (50.8508 mm)	
Blind zone	2.01 in (51 mm)	
Transmission frequency	300 kHz	
Repeat accuracy	1.27 %	
Beam angle	5°	
Minimum size of detected object	Cylinder diameter 2.5 mm - up to 200 mm sensing distance	
Current consumption	40 mA	
Maximum switching current	40 mA (reverse polarity protection)	
Height	1.72 in (43.7 mm)	
Width	0.71 in (18 mm)	
Depth	1.72 in (43.7 mm)	
Length	2.58 in (65.61 mm)	
Product weight	0.07 lb(US) (0.033 kg)	

Environment

product certifications	UL	
marking	CE	
NEMA degree of protection	NEMA 4X (indoor use only)	
IP degree of protection	IP67	
ambient air temperature for operation	-22158 °F (-3070 °C)	
ambient air temperature for storage	-40185 °F (-4085 °C)	
relative humidity	100 % without condensation	
vibration resistance	+/-1 mm conforming to IEC 60068-2-6 1055 Hz	
shock resistance	30 gn in all 3 axes 11 ms conforming to IEC 60068-2-27	
resistance to electromagnetic fields	9.14 V/yd (10 V/m) (level 3) conforming to IEC 61000-4-3	
resistance to fast transients	1 kV (level 3) conforming to IEC 61000-4-4	

Offer Sustainability

WARNING: This product can expose you to chemicals including:	WARNING: This product can expose you to chemicals including:
Diisononyl phthalate (DINP), which is known to the Star of California to cause cancer, and	te Diisononyl phthalate (DINP), which is known to the State of California to cause cancer, and
Di-isodecyl phthalate (DIDP), which is known to the Sta of California to cause birth defects or other reproductive harm.	teDi-isodecyl phthalate (DIDP), which is known to the State of California to cause birth defects or other reproductive harm.
For more information go to www.p65warnings.ca.gov	For more information go to www.p65warnings.ca.gov
Contractual warranty	
Warranty period	18 months

